

**Issued To**  
 Sue Davies  
 St Dogmaels Community Council  
 Dworek  
 Sarnau  
 Llandysul  
 SA44 6PX

**Customer** St Dogmaels Community Council

<b>Number</b> SQ-58	<b>Issue Date</b> 18/10/2022	<b>Expiry Date</b> 17/11/2022
---------------------	------------------------------	-------------------------------

Description	Net Amt	% VAT	VAT	Total
<p><b>PLAY AREA SURFACING REPAIRS:</b></p> <p><b>SURFACE 1 - SWINGS</b></p> <p>Repair of wet pour surface hole by cutting out 0.25m<sup>2</sup> square section, potentially laying new concrete base (if existing base unsuitable), priming base and edges, and laying wet-pour base and top black EPDM layer to appropriate thickness (estimated 70mm).</p> <p><b>SURFACE 2 - AREA INSIDE GATE/ALONGSIDE EDGE OF GRASSED AREA</b></p> <p>Repair of sloping and uneven mulch area by cutting out approx. 10m<sup>2</sup> section, levelling ground on area to be resurfaced, laying new concrete base on area to be resurfaced, installing new wooden edging around this area, raising surrounding ground by gentle slope to meet this area with topsoil and sprinkling with grass seed, priming base and edges of area to be resurfaced, and laying new mulch section to 40mm thickness (colour optional, and please also see attached diagram).</p> <p><b>SURFACE 3 - PLAYBOAT</b></p> <p>Repair of surface wear and sagging on both side entrances by cutting out two 1.9m<sup>2</sup> rectangular sections spanning the whole length of the ship, potentially laying new concrete base (if existing base unsuitable), priming base and edges, and laying wet-pour base and top black EPDM layer to 35mm thickness.</p> <p><b>SURFACE 4 - MULTIPLAY UNIT</b></p> <p>Repair of surface wear and sagging by cutting out entire surfacing around up to 0.8m from unit and underneath unit, potentially laying new concrete base (if existing base unsuitable), priming base and edges, and laying wet-pour base and top black EPDM layer to 65mm thickness.</p>	8,441.05	20.00	1,688.21	10,129.26

## Playground Repairs Ltd

Greenland, Clarbeston Road  
 Haverfordwest, Pembrokeshire, SA63 4QP  
 United Kingdom

**Website** www.playgroundrepairsLtd.co.uk **Telephone** 01437 623023  
**Mobile** 07768 081050 **Email** sales@playgroundrepairsLtd.co.uk

**VAT Registration Number**  
 GB 401323951

Description	Net Amt	% VAT	VAT	Total
<p><b>SURFACE 5 - SECOND MULTIPLAY UNIT</b></p> <p>Repair of surface wear and sagging at base of slide and ramp ladder by cutting out two 1m<sup>2</sup> sections, potentially laying new concrete base (if existing base unsuitable), priming base and edges, and laying wet-pour base and top black EPDM layer to 65mm thickness.</p> <p><b>SURFACE 6 - PIPE</b></p> <p>Removal of existing pipe play equipment, cutting out 36m<sup>2</sup> section, potentially laying new concrete base (if existing base unsuitable), laying new mulch surface (colour optional)</p>				

VAT Rate	Net	VAT
Standard 20.00% (20.00%)	£8,441.05	£1,688.21

<b>Net Amount</b>	8,441.05
<b>VAT Amount</b>	1,688.21
<b>Total</b>	£10,129.26

### Notes

It would be essential to have access to a water supply somewhere in St Dogmaels, in order to carry out concreting work. Please ensure this can be arranged before accepting.

### Terms and Conditions

By accepting this quotation you are deemed to have accepted our TERMS AND CONDITIONS OF PROVISION OF SERVICES, attached to the message through which this quotation was supplied.